

Retaining Wall Engineer's Letter Inspection Report

Please note that on Sep 28, 2022 an inspection was held at the following property for the permit shown below:

PROPERTY ADDRESS: 4693 Corral Dr, Carrollton, TX 75010

Parcel: PRO563854

Application No: PRAS202206593

Application Description: 4693 Corral Dr, Build retaining wall to stop and prevent future

failures caused by a slope failure of the pond embankment across

Permit Type: AS

Inspection ID No: 1041

Inspection Description: Retaining Wall Engineer's Letter

Inspection Result Status: Passed

Inspection Result Comments: Final Engineer's letter uploaded

Most Inspection Penalty Fees are due at CO, however Permits that do not receive a CO have Final Inspections and if reinspection fees are due they must be paid before the system will allow the next Inspection to be scheduled.

Fees may be paid in person at the Building Department Offices at City Hall or with a credit card by visiting the City of Carrollton web site at www.CityofCarrollton.com and navigating to City Services then Building Permit Services.

Rey Guerrero 972-466-5752